


Axial, Lateral & Torsional Vibration Analysis




Type: Cruiser Yacht
 Overall length: 35.40 m
 Overall Beam: 7.60 m
 Engine: 2xCaterpillar 3406C
 440BHP /2100RPM

Axial, lateral & torsional vibration analysis done by presence of a broken shaft and problem with the gearbox.



Torsional model done in TORCAL
 TECNAVIN S.A. Software



Propulsion system representation
 for lateral vibration analysis

Natural frequency's for lateral and torsional analysis

Torsional vibration results from TORCAL software

Frecuencias naturales no amortiguadas - Lateral			
Orden	Vel. de resonancia de motor, rpm		
	Modo 1	Modo 2	Modo 3
	17.3	36.6	54.39
	Hz	Hz	Hz
MOTOR	0.5		
	1		
	1.5	2,076	
	2	1,557	
	2.5	1,246	
	3	1,038	
	3.5	890	1,882
	4	779	1,647
	4.5		1,464
	5		1,318
	5.5		1,198
	6		1,098
	6.5		1,014
	7		941
	7.5		878
	8		824
	8.5		775
	9		732
	9.5		693
	10		659
	10.5		627
	11		599
	11.5		573
	12		816
PROP	1Z	778.5	1647
	2Z		823.50
			1223.78

- Vibratory stresses
- Vibratory torque
- Power loss
- Angular deformation

- Analysis of all propulsion components including engine, damper, couplings, gearbox, shafts, etc.
- Analysis of standard and misfiring condition

Analysis found that 2 of the natural frequencies can be excited by the propeller or engine.

Modo de vibración I (17.3 HZ)				
Armónicos	I - 1Z	I - 2Z	I - 3E	I - 6E
RPM motor	779	-----	1038	-----
Modo de vibración II (36.6 HZ)				
Armónicos	II - 1Z	II - 2Z	II - 3E	II - 6E
RPM motor	1647	824	-----	1098

Frecuencias naturales no amortiguadas - Torsional					
Orden	Velocidad de resonancia de motor, rpm				
	Modo 1	Modo 2	Modo 3	Modo 4	Modo 5
	15.47	46.25	118.8	151.04	213.84
	Hz	Hz	Hz	Hz	Hz
MOTOR	0.5	1,856			
	1	928			
	1.5	619	1,850		
	2		1,387		
	2.5		1,110		
	3		925	2376	
	3.5		793	2037	
	4		694	1,782	2266
	4.5		617	1,584	2,014
	5			1,426	1,813
	5.5			1,296	1,648
	6			1,188	1,510
	6.5			1,097	1,394
	7			1,018	1,295
	7.5			950	1,208
	8			891	1,133
	8.5			839	1,066
	9			792	1,007
	9.5			750	954
	10			713	906
	10.5			679	863
	11			648	824
	11.5			620	788
	12				755
PROP	12	696.15	2081.25		
	22		1040.63		

The normal operation of the propeller using the 4 blades does not present coupling between lateral and torsional frequencies.

Modo y orden torsional	I - 1Z	II - 3E
RPM torsional	696	925
Modo y orden lateral	I - 1Z	II - 2Z
RPM lateral	779	824

TECNAVIN S.A.

navser@gye.satnet.net


Phone: 593-4-2441022
593-9-84166936

Skype:
Franklin.johnny.dominguez.ruiz.1


Garcia Goyena 602 & Chimborazo
Guayaquil – Ecuador

www.tecnavin.com

Analysis results with clutched Propeller. Vulkan courtesy



Analysis results with unclutched propeller. Vulkan courtesy



TECNAVIN S.A.

navser@gye.satnet.net

Phone: 593-4-2441022
593-9-84166936

Skype:
Franklin.johnny.dominguez.ruiz.1

Garcia Goyena 602 & Chimborazo
Guayaquil – Ecuador

www.tecnavin.com

Conclusions:

- Recommend to renew flexible coupling in order to eliminate possible fissure
- Recommend not to operate at velocities close to 900 RPM of propulsion.
- Recommend to change the countershaft design to prevent stress concentration